


Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Nearest MH	Ground Condition	Notification Made?		
D1028-160	Dye	4/23/2009	ADS/TM	S09YY_014MH	Damp	NA		
Address	3607 Cedardale Road		Location	Curb	Status	Public	Source	Catch Basin



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Nearest MH	Ground Condition	Notification Made?		
D1028-160	Dye	4/23/2009	ADS/TM	S09YY_014MH	Damp	NA		
Address	3607 Cedardale Road		Location	Curb	Status	Public	Source	Catch Basin

Observations & Photos

Obs_ID D1028-160-OB01

Nearest MH S09YY_014MH

Comments Dye observed at connection between S09YY_014MH and S09YY_008G2. Infiltration gusher at 9 oclock.



Picture \D1028-160-OB01-P01.jpg

Comments Connection between S09YY_014MH and S09YY_008G2.

Obs_ID D1028-160-OB02

Nearest MH S09YY_014MH

Comments Dye observed 10.3 ft. upstream of S09YY_014MH. Infiltration runner at joint at 9 oclock.



Picture \D1028-160-OB02-P01.jpg

Comments 10.3 ft. upstream of S09YY_014MH along S09YY_008G2.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Nearest MH	Ground Condition	Notification Made?
D1028-160	Dye	4/23/2009	ADS/TM	S09YY_014MH	Damp	NA

Address	3607 Cedardale Road	Location	Curb	Status	Public	Source	Catch Basin
----------------	---------------------	-----------------	------	---------------	--------	---------------	-------------

Obs_ID D1028-160-OB03

Nearest MH S09YY_014MH

Comments Dye observed 13.0 ft. upstream of S09YY_014MH. Infiltration runner at joint at 2 o'clock.

Obs_ID D1028-160-OB04

Nearest MH S09YY_014MH

Comments Dye observed 16.5 ft. upstream of S09YY_014MH. Infiltration runner at joint from 12 to 2 o'clock.



Picture \D1028-160-OB03-P01.jpg

Comments 13.0 ft. upstream of S09YY_014MH along S09YY_008G2.



Picture \D1028-160-OB04-P01.jpg

Comments 16.5 ft. upstream of S09YY_014MH along S09YY_008G2.